

Indian Agency.....

(SUBMIT IN TRIPLICATE)

U. S. Land Office Las Cruces

UNITED STATES

Lease or permit No. 0-31621

Allottee.....

DEPARTMENT OF THE INTERIOR

Lease No.

GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

MexicoMarch 12,....., 1937Well No. 1 is located 330 ft. from N line and 330 ft. from E line of sec. 18NE/4 Sec. 1820S37ET.T.P.M.

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

MonumentLeaNew Mexico

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is 3564 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD 3143 - Lime. Tested shut-off after cementing hole in 9-5/8" casing
206' down by applying 1200# pressure after drilling
cement plug. Tested Ok.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Phillips Petroleum CompanyAddress Box 1390 Midland, TexasBy /s/ Earl GriffinTitle Dist. Supt.