COPY TO O. C. S.

Form 9–331 Dec. 1973 UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	Form Approved. Budget Bureau No. 42–R1424 5. LEASE LC-031736 (b) 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME
1. oil well □ gas well □ other	8. FARM OR LEASE NAME Gillully B Federal RA A 9. WELL NO.
2. NAME OF OPERATOR	8
Amoco Production Company 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Monument Ladach
P. C. Box 58, Hobbs, NM 88240 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA
below.)	22-20-37
AT SURFACE: (Unit C, NE/4, NW/4) Sec. 22 AT TOP PROD. INTERVAL: 660' FNL X 1980' FWL AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE Lea NM
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3561' RB
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF	
FRACTURE TREAT	
	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
MULTIPLE COMPLETE Image: Complete <	
ABANDON*	
Moved in service unit 6-16-81. Ran a base g Perforated 5208'-20' w/2 SPF. Spotted 42 ga Packer set at 4955'. Acidized with 3400 gal Tubing landed at 5193'. Seating nipple set well to production.	amma ray log 4800-524 5'. llons 15% Acid at 522 l'. lons 15% NEFE acid.
O+6-USGS, H 1-Hou 1-Susp 1-GPM	
Subsurface Safety Valve: Manu. and Type	Set @ Ft
18. I hereby ertify that the foregoing is frue and correct	
SIGNED Sug Mitchelf TITLE Admin. Analy	st6-30-81
ACCEPTED FOR RECORD ^{pace} for Federal or State off APPROVED BY	
U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICORE Instructions on Reverse S	Side

يبريا ومناد المعامة وا

يتجنيلانه ويدفرن

ورايتك م

.

. .