

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE  
(Other instructions on  
reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME <b>SEMU</b>
2. NAME OF OPERATOR <b>CONTINENTAL OIL COMPANY</b>		8. FARM OR LEASE NAME <b>SEMU PENN</b>
3. ADDRESS OF OPERATOR <b>Box 460, Hobbs, N.M. 88240</b>		9. WELL NO. <b>7</b>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <b>1980' FNL &amp; 1980' FWL OF SEC. 23</b>		10. FIELD AND POOL OR WILDCAT <b>CASS PENN</b>
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <b>Sec. 23, T-20S, R. 37E</b>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <b>3538' DF</b>		12. COUNTY OR PARISH <b>LEA</b>
		13. STATE <b>N.M.</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
(Other) <b>CONVERT TO SUD</b>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Checked csq. for leak, found none. Cleaned out to 7690'. Ran 3 1/2" plastic lined tubing to 7576'. Set plcr. @ 7576'. Pmpd 180 bbls. phr. fluid down annulus. Shut well in pending completion of SEMU Penn SUD system. Work started 6-9-75, completed 6-17-75

Approved by Order # R-5026

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE SR. ANALYST DATE 8-12-75

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

ACCEPTED FOR RECORD

AUG 19 1975

U. S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

USGS-5, NMFL-4, File