

HUMBLE OIL & REFINING COMPANY - HUMBLE STATE AOGIES NO. 1 - FORM C-103 (Continued)

Detailed Account of Work Done, Nature and Quantity of Materials Used and Results Obtained.

7. Unseated packer and reset same at 3794.
8. Treated open hole section 3794 to 3850 with 10,000 gallons El Paso Residue oil with 0.025 pounds MarkII Adomite per gallon and one pound 20-40 sand per gallon. Average injection rate of 9.6 BPM. Maximum pressure 5800 pounds, Minimum pressure unknown. Treatment by Halliburton.
9. Pulled frac tubing and reran 2" tubing, rods and pump, started well pumping, released unit.
10. Recovered all load oil.
11. Well completed as a pumping oil well.