NUMBER OF COPI	ER SECEIVED	
DIS	TRIBUTION	
BANTA FF		
FILE		
U.S.G.S.		
LAND OFFICE		
TRANSPORTER	OIL	
	648	
PROBATION OFFI	C &	
<b>63.6</b> 0.4.700		

## NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103 (Rev 3-55)

## MISCELLANEOUS REPORTS ON WELLS

GSubmit to appropriate District Office as per Commission Rule 1106)										
Name of Company HUMBLE OIL & REFINING COMPANY Box 2347, Hobbs, New Mexico										
ate Aggies		Well No.	Unit Letter D	Section 31				R-37-E		
ormed ~63	Pool Eunice			C	County Lea					
Beginning Drilling Operations Casing Test and Cement Job Other (Explain):										
☐ Plugging ☐ Remedia: Work										
Detailed account of work done, nature and quantity of materials used, and results obtained.  1. Pulled rods and tubing.  2. Fired string shot over interval 3763-3340'.  3. Set packer at 3760'-treated open hole from 3760-3845' with 1000 gal NE acid.  4. Pulled packer and tubing.  5. Run tubing and rods-placed well on pump.										
Position   Company   Compa										
7	3º7.5		-		3738-3845		Completion Date 2-9-51			
	-		On Still	5 <b>–1,</b> /2	CΙ	Off String	-	738		
rval(s)						······································				
Open Hole Interval 3733-3845 Producing Formation(s) Gravburg										
	<del></del>		OF WOR	COVER		1				
Date of Test	Oil Production BPD					GOR Cubic feet/B	ы	Gas Well Potential MCFPD		
1-8-63	13 ·		4.3			3038		<b></b>		
4-15-63	28	15	155		··		-			
OIL CONSERVATION COMMISSION  I hereby certify that the information given above is true and complete to the best of my knowledge.										
pproved by Name										
<del></del>			i .	Position						
Company HUMBLE OIL & REFINING COMPANY										
	Drilling Operation of work done, named of rods and to string shot backer at 376 and packer and bubing and roman of the string shot backer at 376 and packer and bubing and roman of the string shot backer at 376 and packer and bubing and roman of the string shot backer at 376 and packer and bubing and roman of the string shot backer at 376 and packer and bubing and roman of the string shot backer at 376 and packer and bubing and roman of the string shot backer at 376 and packer and bubing and roman of the string shot backer at 376 and packer at 376	S. B. Carlson  FILL IN BE  To a 20/5  Tubing Depth  To a 20/5  To a 20/5  Tubing Depth  To a 20/5  To a 20/	S. B. Carlson  FILL IN BELOW FOR REPORTS and packer and tubing. This game and rods-placed well on pum and rods and tubing. The packer and tubing and rods-placed well on pum and rods-placed well on p	Address  I 2 REFINING COMPANY  Atte Aggies  THIS IS A REPORT OF: (Check Drilling Operations  THIS IS A REPORT OF: (Check Drilling Operations  TRANSIS A REPORT OF: (Check Drilling Operations  TRANSIS A REPORT OF: (Check This is a REPORT OF: (Check Drilling Operations  TRANSIS A REPORT OF: (Check This is a Report of the Act of t	Company   Address   Box 27	Submit to appropriate District Office as per Company   Address   Box 2347, Nobserval   Carefin   Submit   Address   Box 2347, Nobserval   Carefin   Submit   Submit	Submit to oppropriate District Office as per Commission Rule   Address	Submit to appropriate District Office as per Commission Rule 1106)   Address		