HUMBLE OIL & REFINING COMPANY - HUMBLE STATE AGGIES NO. 10 - FORM C-103 (Continued)

Detailed Account of Work Done, Nature and Quantity of Materials Used, and Results Obtained.

- 8. Ran 2" tubing, set at 3735, ran rods and pump, started well pumping, but failed.
- 9. Loaded tubing with lease oil, pressured up to 700 pounds, tubing held OK. Unseated pump, pumped oil into formation, reset pump and started well pumping. Failed to pump.
- 10. Pulled rods and pump, cleaned frac sand out of pump, reran rods and pump, well failed to pump, long stroked well with pulling unit, started pumping. Released unit.
- 11. Recovered all load oil. Testing well.
- 12. Well completed as a pumping oil well.