

HUMBLE OIL & REFINING COMPANY'S

Humble State Aggies #10

SW-1/4 of Section 31, Township 20-South
Range 37-East, Lea County, New Mexico.

DEVIATION SURVEYS

Acid bottle test at 600' - hole straight
Acid bottle test at 850' - deviation 1 degree
Acid bottle test at 1050' - deviation 1 degree
Acid bottle test at 1500' - deviation 1 degree
Acid bottle test at 1700' - hole straight
Acid bottle test at 2000' - deviation 1 degree
Acid bottle test at 2250' - deviation 1 degree
Acid bottle test at 2500' - deviation 1 degree
Acid bottle test at 3000' - hole straight.

DRILL STEM TESTS

N o n e