

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 032096(a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

CONTINENTAL OIL COMPANY

3. ADDRESS OF OPERATOR

Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

810' FNL & 660' FWL OF SEC. 27

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

LOCKHART A-27

9. WELL NO.

8

10. FIELD AND POOL, OR WILDCAT

BLINEBRY (GAS)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SEC. 27, T. 21S, R. 37E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3410' DF

12. COUNTY OR PARISH

LEA

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐

PULL OR ALTER CASING

☐

FRACTURE TREAT

☐

MULTIPLE COMPLETE

☐

SHOOT OR ACIDIZE

☐

ABANDON*

☐

REPAIR WELL

☐

CHANGE PLANS

☐

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐

REPAIRING WELL

☐

FRACTURE TREATMENT

☐

ALTERING CASING

☐

SHOOTING OR ACIDIZING

☐

ABANDONMENT*

☐

(Other)


REPAIR COMMUNICATIONS ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Found leak @ csq. head. Seal in 9 5/8" x 7" annulus
bad. Replaced 7" csq slips & seal. Ran Baker
Lock-set plcr & set @ 6320. Tested 7" csq &
wellhead w/1900 psi for 1/2 hr. Held. Ok.
Work started 1-10-75, completed 1-30-75.

18. I hereby certify that the foregoing is true and correct

SIGNED



TITLE

SR. ANALYST

DATE

2-3-75

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

*See Instructions on Reverse Side

ACCEPTED FOR RECORD

FEB 17 1975

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICOUSGS-5, NMFSU
HOBBS-4, File