

## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

## Indicate Nature of Report by Checking Below

REPORT ON BEGINNING	REPORT ON RESULT OF TEST	REPORT ON
DRILLING OPERATIONS	OF CASING SHUT-OFF	REPAIRING WELL
REPORT ON RESULT	REPORT ON RECOMPLETION	REPORT ON
OF PLUGGING WELL	OPERATION	(Other)

May 27, 1955 Hobbs, New Mexico

Following is a report on the work done and the results obtained under the heading noted above at the

Ctanolind Gil and Gas Company	W	. H. Turner				
(Company or Operator)	(Lease)					
J. P. Gibbins (Contractor)	, Well No3	in the				
т. 21-5., r. 37-6., NMPM, Tubb (Gas)	Pool,	Lea	County.			
The Dates of this work were as folows: March 24, 1955 to May 22, 1955						
Notice of intention to do the work (was) (was submitted on For	C-103 m xxxxx on 3-31-5	5				
	Cr	oss out incorrect words	, , , , , , , , , , , , , , , , , , ,			

and approval of the proposed plan (was) (wasyond obtained,

## DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

In accordance with Form C-103 filed Harch 31, 1955, the following work was performed and results obtained:

Set bridging plug at 7045' to abandon AcConnack pay and squeezed open hole below plug with 150 sacks cement. Perforated intervals 6750' to 7045' with 2 shots per foot opposite the Wantz-Abo pay. After sand-oil fracing with 10,000 gallons plus 1% of sand per gallon and testing, the Wantz-Abo proved to be non productive.

In order to recomplete as a gas well in the Tubb gas pay, a bridge plug was set at 6300' and capped with 10' of cement. Perforated intervals 6240-6255, 6210-6230, 5150-6200, 5115-6140 with 4 shots per foot and sand-oil fraced with 20,000 gallons oil mixed with 20,000# sand. On test 5-22-55, well flowed 1835 ECFG, 114 B0, 50 gravity in 24 hrs. on 12/64" choke. TPF - 1600, CFF - 1800 psi.

Witnessed byF	tanolind	Company) Tool Pusher (Title)
Approved: OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge. Original Signed by Name RALPH L. HENDRICKSON
(Name)	анарананананананананананананананананана	Position_Field_Superintendent RepresentingStanolind_Gil_and_Gas_Company
(Title)	(Date)	Address