

19139

EUNICE WELL SERVICING CO.

CUSTOMER

EUNICE, NEW MEXICO

Order No. _____

AUTHORIZATION FOR WORK

COMPANY Chenman USA, Inc. LEASE CD-11 WELL NO. 159

ADDRESS _____ POOL _____

DESCRIPTION OF WORK

Bled down well, packer dragged pulling out 12' hole, stood back 169' to. Day down 44 yds, found two holes, one joint below parallel anchor, and 24 below anchor, lay down packer, cut joint with hole, cap well off, shut down.

TIME STARTED 6:30 AMTIME STOPPED 11:30 AM

	PULLED OUT	RUN IN WELL
QTY. & SIZE PADDLE RODS		
QTY. & SIZE PLAIN RODS		
QTY. & SIZE ROD SUBS		
QTY. & SIZE TUB.	<u>200-23/8</u>	
QTY. & SIZE TUB. SUBS		
SIZE & NO. OF PUMP		
OTHER		

	NAME	TO 9000	BELOW 9000	RATE	
DOUBLE DRUM UNIT	POLE NO. <u>1</u> DERRICK NO. <u>1</u>	<u>5</u>			
PICKUP & TOOLS		<u>5</u>			<u>505.00</u>
OPERATOR	<u>Jackie Ruttle</u>	<u>5</u>			
HELPER OR DERRICKMAN	<u>Donny Newton</u>	<u>5</u>			
HELPER	<u>Genaro Villa</u>	<u>5</u>			
HELPER	<u>Juan Cortez</u>	<u>5</u>			
POWER TONGS					
FISHING TOOL					
WIPER RUBBER					
ROD STRIPPER					
STANDING VALVE					

	SIZE	TYPE	QTY.	PRICE EA	EXT.	DISC.	
STRIPPER RUBBER							
SWAB CUPS							
HYD. O.S.							

SUB TOTAL

TAX

TOTAL

DATE

6-18-93

ACCEPTED

