

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Oil-Oil Dual	7. Unit Agreement Name Central Drinkard Unit
2. Name of Operator GULF OIL CORPORATION	8. Farm or Lease Name Mobil's Hardy #6
3. Address of Operator P. O. Box 670, Hobbs, NM 88240	9. Well No. 159
4. Location of Well UNIT LETTER D 660 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 29 TOWNSHIP 21S RANGE 37E N.M.P.M.	10. Field and Pool, or Wildcat Drinkard-Paddock
15. Elevation (Show whether DF, RT, GR, etc.) 3491' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Repair Down Hole Tubing Leaks

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6650' TD 6500' PB Pres test tbg w/PT showed to have tbg leak. Pulled rods & pump. Re-tested w/SV & PT, still have tbg leak. Pulled long string, tested long string back in hole to 5000# using Hydrotect. Ppd 1000 gal acid (15% NEFE inhib) dn long string to clean up scaled and flush w/26 BFW. Ran Mobil's tbg, pmp & rods as before; ran Gulf's pmp & rods as before. Checked pump action on both strings, cleaned loc, rlsd unit & crew.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. P. Liles Jr. TITLE Area Engineer DATE 3-31-80

APPROVED BY _____ TITLE _____ DATE APR 1 1980

NOTATIONS OF APPROVAL, IF ANY: