ENERGY AND MINERALS DEPARTMEN	OIL CONSERVATION DIVIS	
us, or conics nectives		Form C-103
OISTRIBUTION	P. O. BOX 2088	Revised 10-1-78
BANTA FE	SANTA FE, NEW MEXICO 8750	
FILE		Sa. Indicate Type of Lease
LAND OFFICE		State Fee X
OPERATOR		5. State Oll & Gas Lease No.
Urenarion		
SUNDR' SUNDR' SUNDR'	RESERVOIR.	
1.		7. Unit Agreement Name
	Central Drinkard Unit	
Name of Operator	OTHER-	8. Farm or Lease Name
GULF OIL CORPORATION	*Sun Oil V. Linam	
GULF UIL CORFORATION	9. 's'-11 No.	
P. O. Box 670, Hobbs,	ÎÕ6	
A. Location of Well	10. Field and Pool, or Wildcat *Penrose Skelly	
	980 rect room Drinkard	
UNIT LETTERD	660 VEET FROM THE North LINE AND 19	
6° it	н <u>29</u> точизнія <u>21</u> кансе <u>3</u>	
THE OASL LINE, SECTIO	N YOWNSHIP RANGE	<u></u>
mmmmmmm.	12. County	
	15. Elevation (Show whether DF, RT, GR, etc.)	Lea
	. 3475' GL	
Te. Check J	Appropriate Box To Indicate Nature of Notice	e, Report or Other Data
NOTICE OF IN	TENTION TO:	SUBSEQUENT REPORT OF:
	r	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON	COMMENCE DRILLIN	
PULL OR ALTER CABING	CHANGE PLANS CASING TEST AND C	
	OTHER Kepa	
0THER		Acz

Pkr leakage tst indicated comm between Drk & Pen Skelly zones; Drk would not pump. Ppd 35 bbl FW dn long string to tst for tbg leak; would not load-vac. Unseated pump on long string. Hot oiled rods w/30 bbl lse oil to clean up paraffin. POH w/rods in short string. Rlsd pkr. Killed well w/50 bbl 8.6# GKF. POH w/long string. LD & replaced 26 jts badly corroded & pitted tbg below split jt. RIH w/long string. Killed well w/25 bbl GKF. Aczd Drk OH 6521'-6670' w/1000 gals 15% double inhib HCL dn 2-3/8" tbg as follows: Loaded tbg w/800 gal acid. Ppd remaining acid @ 1½ BPM & 1000#. Flshed w/27 bbl 8.6# GKF @ 1½ BPM & 1500#. End of flsh pres, dcrs to 1200#, ISIP 500#, 5 min vac. RIH w/short string. RIH w/rods for long & short string. Spaced out & hung on. Drk ppg to btry 17 hrs NG. Drk ppd 26 BO, tr BW & TSTM MCF in 24 hrs on tst dated 4-6-80. 6 SPM X 100" oil gvty 38.6 @ 60 F CP-pkr, TP 35#, 2" W/0 ck 4"x3/4" plate, 2-3/8" tbg w/pkr @ 6459'. Complete after repairing communication & acid stimulation.

18.   hereby cert	ify that the information above is true and c	complete to the best o	f my knowledge and belief.	
*ICHED	. A. Bekes, Jr.	YIYLE	Area Engineer	PATE 4-17-80
APPROVED 87	joba tranjala Goologist	ŤĮYLČ		DATE APR 2 1 1980
CONDITIONS O	F APPROVAL, IF ANYL			