

OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

RECEIVED
JUN 2 1947
HOBBS OFFICE

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL REPORT ON RESULT OF TEST OF CASING SHUT-OFF REPORT ON RESULT OF PLUGGING OF WELL	REPORT ON REPAIRING WELL REPORT ON PULLING OR OTHERWISE ALTERING CASING REPORT ON DEEPENING WELL Report on setting Casing X
--	---

May 30, 1947 Date Monument, New Mexico. Place

OIL CONSERVATION COMMISSION,
SANTA FE, NEW MEXICO.

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the _____

~~Amerada Petroleum Corporation~~ J. G. Hare Well No. 6 in the _____
Company or Operator Lease

~~N.M. SW~~ of Sec. 33, T. 21S, R. 37E, N. M. P. M.,
~~Brunson~~ Field, Lea County.

The dates of this work were as follows: May 29 and 30, 1947

Notice of intention to do the work was ~~(discuss)~~ submitted on Form C-102 on May 29, 1947
and approval of the proposed plan was ~~(was not)~~ obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

2765' Total Depth Lime, Ran 9 Jts 8 5/8" OD 32#, 8 V Thd Smlss, 23 Jts 8 5/8" OD 32# LW, 10 V Thd and 66 Jts 8 5/8" OD 32#, 8 V Thd Seamless and 13 jts 8 5/8" OD 32#, 8 RT Seamless Casing, Total of 111 joints, first ten joints were welded and rest of joints spot welded on top of collar, and Casing set at 2759' ~~and cemented~~ and cemented with 1500 Sacks Atlas Com on Bulk, with 1000 sacks 3% Howco gel, and 50 sacks Incor and plug pumped to 2709' at 9AM, May 30, 1947.

Witnessed by E. F. Furse Amerada Pet. Corp., Foreman
Name Company Title

Subscribed and sworn before me this _____

I hereby swear or affirm that the information given above is true and correct.

30 day of May, 19 47

Name W. H. Taylor

Will H. Taylor
Notary Public

Position Asst. Dist. Supt.

Representing Amerada Pet. Corp.,
Company or Operator

My commission expires _____

Address Drawer D, Monument, New Mexico.

Remarks:

APPROVED

Date JUN 2 1947

Ray. Yarbrough
Name
Oil & Gas Inspector
Title