

|                           |     |
|---------------------------|-----|
| NUMBER OF COPIES RECEIVED |     |
| DISTRIBUTION              |     |
| SANTA FE                  |     |
| FILE                      |     |
| U.S.G.S.                  |     |
| LAND OFFICE               |     |
| TRANSPORTATION            | OIL |
|                           | GAS |
| PRODUCTION OFFICE         |     |
| OPERATOR                  |     |

**NEW MEXICO OIL CONSERVATION COMMISSION**  
**MISCELLANEOUS REPORTS ON WELLS**

**FORM C-103**  
(Rev 3-55)

(Submit to appropriate District Office as per Commission Rule 1106)

|  |  |                                    |                         |   |                         |                      |  |
|--|--|------------------------------------|-------------------------|---|-------------------------|----------------------|--|
| Name of Company<br><b>Pan American Petroleum Corporation</b> |  |                                    |                         | Address<br><b>Box 68, Hobbs, New Mexico</b> |                         |                      |  |
| Lease<br><b>Hugh Corrigan</b>                                |  | Well No.<br><b>2</b>               | Unit Letter<br><b>I</b> | Section<br><b>33</b>                        | Township<br><b>21-S</b> | Range<br><b>37-E</b> |  |
| Date Work Performed<br><b>1-31-61 thru 2-3-61</b>            |  | Pool<br><b>Brunson - Wants Abe</b> |                         |   |                         | County<br><b>Lea</b> |  |

THIS IS A REPORT OF: (Check appropriate block)

- |  |   |   |
|--|---|---|
| <input type="checkbox"/> Beginning Drilling Operations | <input type="checkbox"/> Casing Test and Cement Job | <input type="checkbox"/> Other (Explain): |
| <input type="checkbox"/> Plugging                      | <input type="checkbox"/> Remedial Work              | <b>Recomplete in Wants Abe Pool</b>       |

Detailed account of work done, nature and quantity of materials used, and results obtained.

The Brunson (Ellenburger) pool has been temporarily abandoned and well recompleted in the Wants Abe Pool. Brunson temporarily abandoned by setting Baker Model "D" permanent production packer at 7350', running tubing and shutting well in. Abe zone completed by perforating 7018-38; 7109-29; 7175-95; 7223-38; 7260-60; with 2 shots per foot and acidizing with 7000 gallons 15% acid. Ran tubing to 7007', cased in and completed.

Well produced 165 barrels of oil and 70 barrels of water in 24 hours on 19/64" choke.

Brunson Zone SI, and allowable cancellation requested pending dual completion hearing.

|                                      |                                 |  |
|--------------------------------------|---------------------------------|--|
| Witnessed by<br><b>T. J. Thigpen</b> | Position<br><b>Area Foreman</b> | Company<br><b>Pan American Petroleum Corporation</b> |
|--------------------------------------|---------------------------------|--|

**FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY**

| ORIGINAL WELL DATA     |              |                        |                    |                 |
|------------------------|--------------|------------------------|--------------------|-----------------|
| D F Elev.              | T D          | P B T D                | Producing Interval | Completion Date |
| Tubing Diameter        | Tubing Depth | Oil String Diameter    | Oil String Depth   |                 |
| Perforated Interval(s) |              |                        |                    |                 |
| Open Hole Interval     |              | Producing Formation(s) |                    |                 |

**RESULTS OF WORKOVER**

| Test            | Date of Test | Oil Production BPD | Gas Production MCFPD | Water Production BPD | GOR Cubic feet/Bbl | Gas Well Potential MCFPD |
|-----------------|--------------|--------------------|----------------------|----------------------|--------------------|--------------------------|
| Before Workover |              |                    |                      |                      |                    |                          |
| After Workover  |              |                    |                      |                      |                    |                          |

**OIL CONSERVATION COMMISSION**

I hereby certify that the information given above is true and complete to the best of my knowledge.

|                                       |  |
|---------------------------------------|--|
| Approved by<br><i>Fred A. Clement</i> | Name<br><b>Original Signed by:<br/>V. E. STALEY</b>  |
| Title                                 | Position<br><b>Area Superintendent</b>               |
| Date                                  | Company<br><b>Pan American Petroleum Corporation</b> |