- CONTRACT.			(Form C-103) (Revised 7/1/52)
NUPLICALL	IL CONSERVATION	COMMISSION	
	anta Fe, New Mexico		A CONTRACTOR
			SIN

MISCELLANEOUS REPORTS ON

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of c It of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agen See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING	REPORT ON RESULT OF TEST	REPORT ON
DRILLING OPERATIONS	OF CASING SHUT-OFF	REPAIRING WELL
REPORT ON RESULT	REPORT ON RECOMPLETION	REPORT ON
OF PLUGGING WELL	OPERATION	(Other)

(Date)

(Place)

Address Gramor 580 Bunice, Hollers

Following is a report on the work done and the results obtained under the heading noted above at the

.......

(Date)

(Company or Operator)	Lease).	
J_C_Clower		.¼ of Sec
(Contractor) 21 87 Г, R, NMPM.,	Pool,	County
The Dates of this work were as folows:	1 7, 17, 58	
Notice of intention to do the work (was) (cd on Form C-102 on	, 19
and approval of the proposed plan (was) (was not) obtained		
20 sacks of coment was pumped on Pipe was shot off at 900 ft. an	filled with water, then 40 sacks of mud : at, pull tubing out, and at 600 ft, pipe was pulled up to 500f and 50 sacks commont pumped out, tubing w	t.
	医颈肌 過行 医医肠下痛 切开的现在分词 计组织的存在 计复杂力 计复数上标的 神	
pulled up to 600 ft. and 30 sach then pulled, 609 ft. of 7 in. re	ks consult yumped out. Tubing and pipe we	
pulled up to 600 ft. and 30 sach then pulled, 609 ft. of 7 in. re	ks comput yumped out. Tubing and pipe m.	
pulled up to 600 fto and 50 sadi then pulled, 609 ft. of 7 ino re Top of surface pipe was then cen	ks consult yumped out. Tubing and pipe we	
pulled up to 600 fto and 50 sadi then pulled, 609 ft. of 7 ino re Top of surface pipe was then cen	ks consult yumped out. Tubing and pipe we	
pulled up to 600 fto and 30 sadi then pulled. 609 fto of 7 ino re Top of surface pipe was then cen ground.	ks consult yumped out. Tubing and pipe we	
pulled up to 600 fto and 50 sadi then pulled, 609 ft. of 7 ino re Top of surface pipe was then cen	ks consult yumped out. Tubing and pipe we	
pulled up to 600 fto and 30 sadi then pulled. 609 fto of 7 ino re Top of surface pipe was then cen ground.	is commut yumped out. Tubing and pipe we seevered. mented with 4 in. pipe marker extending J.C.Clower	.e a.bove
pulled up to 600 fto and 30 sadi then pulled. 609 fto of 7 ino re Top of surface pipe was then cen ground. Witnessed by	Locolower (Company) I hereby certify that the information given above	.e a.bove

(Title)