

(SUBMIT IN TRIPLICATE)

Federal-H. A. Reinath

Water Well #1

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
MINED FORM

Artesia, N. M.
Land Office LE-053056
Lease No. _____
Unit 1
JUL 1 1944
RECEIVED
HOBBBS OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR <u>Water Well</u> <u>X</u>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT..... <u>1</u>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA.)

Midland, Texas, July 10

44

Well No. 1 is located 2276 ft. from N line and 1980 ft. from E line of sec. 8
1/4 of NW 1/4 of Sec. 8 21-0 38-X

South Main (Field) Midland (County or Subdivision) 3575 St. New Mexico (State or Territory)
(Twp.) 10a (Range) (Meridian)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Made effort to pull 8-5/8" casing but failed in attempt. Left casing in hole.
Filled hole from bottom to top with heavy-sand-laden fluid and cemented over top
of hole with 5 sacks cement.
Total depth 333'.
8-5/8" casing run to depth of 205'.
Work completed 7-1-44.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Humble Oil & Refining Company

Company _____

Box 1600

Address _____

Midland, Texas

By _____

Title _____

Division Superintendent