

(SUBMIT IN TRIPLICATE)

Federal-H. A. Edinath

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Artesia, N. M.
Lease No. 10-058156
Unit 10-058156

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Midland, Texas, July 1, 1944

WATER Well No. 1 is located 227 1/2 ft. from N line and 1920 ft. from W line of sec. 8
SE 1/4 of NW 1/4 Sec. 8 21-3 10-R
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
South Madine Wildcat 101 New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3575 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Made an effort to plug 8-5/8" casing but failed in attempt. Left casing in hole. Filled hole from bottom to top with heavy mud-laden fluid and cemented over top of hole with 5 sacks cement.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Marble Oil & Refining Company
Address Box 1600,
Midland, Texas
By [Signature]
Title Division Superintendent