

HOBBS OFFICE O.C.C.
NEW MEXICO OIL CONSERVATION COMMISSION

Dec 5 7 49 AM '66

Form O-100
Supersedes Old
O-100 and O-103
Effective 10-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK OR TO DIFFERENT RE-ENTRY.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR OTHER WELLS.

GAS ☐
WELL ☐

OTHER-

AMERICAN PETROLEUM CORPORATION

68, Hobbs, New Mexico 88240

D 990 FEET FROM THE NORTH LINE AND 660 FEET FROM

WEST LINE, SECTION 36 TOWNSHIP 21-S RANGE 37-E

15. Elevation (Show whether DF, RT, GR, etc.)

3379 R.D.B.

12. County

LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PLUG AND ABANDON ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPERATIONS ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed operations) SEE RULE 1103.

In August 3, 1966, well failed to produce due to an apparent tubing and casing collapse. Repair costs and depleted producing prospects preclude remedial considerations. Proposed to Plug and abandon as follows:

Pull tubing from free point. Cut and pull 7" casing from free point or near point from which tubing pulled. Spot 50 st. cement plug in and out of casing seat. Spot 10 st. at surface and erect R/A marker. Make final cleanup and restore ground to contour.

15-0300.

15-0300, Baker Model 2 @ 5900'

15724-5800, Various intervals

13 7/8" CSA 293' Circ 2" TB @ 6850'
4 1/2" CSA 2337' 3255'
7" CSA 600' 1505'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

TITLE

Area Supervisor

DATE

11-30-66

TITLE

DATE

APPROVAL, IF ANY: