

OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	<input checked="" type="checkbox"/>		

2 / 28 / '50

Date

Hobbs

Place

OIL CONSERVATION COMMISSION,
SANTA FE, NEW MEXICO

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the _____

C. L. Noraworthy, Jr. Sinclair-Waldrop Well No. I in the _____
Company or Operator Lease
C-NE of Sec. I of Sec. I, T. 20S, R. 38E, N. M. P. M.,
House Field, Lea County.

The dates of this work were as follows: 2 / 27 & 28 / '50

Notice of intention to do the work was (was ~~not~~) submitted on Form C-102 on 2 / 27 1950
and approval of the proposed plan was (was ~~not~~) obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Spotted 15 sax cement on top of plug set at 4403'. Out casing at 4400' with McCullough jet. Could not pull. Out again at 3915 and pulled. Recovered 3915'. After pulling casing run tubing and conditioned hole with 9.5# mud and spotted 15 sax cement at 3608'. Put 10 sax in top of salt string in which permanent marker was set. Will clean location of rubbish and fill pits as soon as Contractor moves rig and equipment from location.

Witnessed by _____

Name

Company

Title

Subscribed and sworn before me this _____

I hereby swear or affirm that the information given above is true and correct.

28 day of February 1950

Name Jas. O. JarmanPosition Supt.Representing C. L. Noraworthy, Jr.

Company or Operator

My commission expires _____

My Commission Expires June 28, 1953

Address First National Bank Bldg.,Dallas 1, Texas.

Remarks:

Name

Title