

(Title)

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

	Indicate Nature of Report by Checking Bo	elow
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RESULT OF TEST OF CASING SHUT-OFF	REPORT ON REPAIRING WELL
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RECOMPLETION OPERATION	REPORT ON (Other)
	June 12, 1956	Imbbook, Texas
Following is a report on the work of	done and the results obtained under the heading	noted above at the
DeKalb Agricultural Asma	. Inc. & Magnolia Petroleum Co.	Nancy G. Stevall
Western Drilling Company	, Well No 1-G	in the
20-5 ., R 38-E , NMPM.,	hdesignated Pool,	County
The Dates of this work were as follows:	June 12, 1956	
Notice of intention to do the work (was)	(weeket) submitted on Form C-1991n	(Cross out incorrect words)
		(Ologe Cut Interior were)
and approval of the proposed plan (was)	(biogi) obtained.	
DETAIL	ED ACCOUNT OF WORK DONE AND RESU	
5-1/2" casing was run	at 3989° and cemented with 250 and tested with 1000% pump press	sacks. After waiting on cement
5-1/2" casing was run the plug was drilled a	at 3989 and cemented with 250 and tested with 1000 pump pressured. Western D. Illing Co. (Company)	sacks. After waiting on cement ure for one hour. No less in management. Tool Pusher
5-1/2" casing was run the plug was drilled a pressure, so drilling Witnessed byFrank.Eldridge (Name)	at 3989 and cemented with 250 and tested with 1000 pump pressured. Western D. Illing Co. (Company)	sacks. After waiting on cement are for one hour. No less in Tool Pusher (Title) hat the information given Afove is try and complete

(Date)