

DISTRICT I

1625 N. French Dr., Hobbs, NM 88240

DISTRICT II

811 S. First, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87504

WELL API NO. 30-025-07787
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.
7. Lease Name or Unit Agreement Name Fred Turner Jr. "A"
8. Well No. 4
9. Pool Name or Wildcat Skaggs Grayburg
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3564' DF

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER TA'd
2. Name of Operator Amerada Hess Corporation
3. Address of Operator P.O. Box 840, Seminole, TX 79360
4. Well Location Unit Letter <u>F</u> : <u>1987</u> Feet From The <u>West</u> Line and <u>1980</u> Feet From The <u>North</u> Line Section <u>18</u> Township <u>20S</u> Range <u>38E</u> NMPM <u>Lea</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3564' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input checked="" type="checkbox"/> TA'd Well.
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-16 thru 6-28-2001

MIRU Aries Well Svc. pulling unit. Removed wellhead, installed BOP & TOH w/tbg. Ran 4-3/4" gauge ring to 3000'. TIH w/CIBP & set at 2860'. Circ. pkr. fluid & press tested csg. to 500 PSI for 30 min. Held OK. Removed BOP & installed wellhead. RDPU & cleaned location. Opened intermediate csg. & press. up on csg., had communication between intermediate & prod. csg. Closed in well 5-17 for repair. 6-28-01: Dug out around wellhead & found that risers that came to surface were from prod. csg. Press. tested csg. to 520 PSI for 30 min. Held OK. Chart attached. TA'd well.

Amerada Hess Corporation respectfully request a TA'd status on well to evaluate for future work.

This Approval of Temporary
Abandonment Expires 7/12/06

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <u>Roy L. Wheeler, Jr.</u>	TITLE <u>Bus. Svc. Spec. II</u>	DATE <u>07/02/2001</u>
TYPE OR PRINT NAME <u>Roy L. Wheeler, Jr.</u>	TELEPHONE NO. <u>915-758-6778</u>	

(This space for State Use)

APPROVED BY _____	TITLE _____	DATE _____
-------------------	-------------	------------

CONDITIONS OF APPROVAL, IF ANY: