## P.O. BOX 1980 10BBS, NEW MEXICO 88240

Form 3160-5 (June 1990)	UNITED STATI DEPARTMENT OF THE BUREAU OF LAND MAI	INTERIOR	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993  5. Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals			6. If Indian, Allottee or Tribe Name
	SUBMIT IN TRIPL	7. If Unit or CA, Agreement Designation	
1. Type of Well Oil Well 2. Name of Operator	Gas Souher Injection	8. Well Name and No.  SEMU Burger B No. 71 9. API Well No.	
20000 Inc. 3. Address and Telephone No.  10 Desta Dr. Ste 100W. Midland. TX 79705 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  660' FSL & 1830' FEL			30-025-07797  10. Field and Pool, or Exploratory Area  Skaggs Drinkard  11. County or Parish, State
Sec. 18, T-20S, R-38E  CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT			Lea DATA
			11, OR OTHER DATA
S S S S S S S S S S S S S S S S S S S	E OF SUBMISSION  lotice of Intent  ubsequent Report  inal Abandonment Notice  d or Completed Operations (Clearly state all pertinent details to locations and measured and true vertical depths for all	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other Casing Integrity Tes	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form 1 g any proposed work. If well is directionally drilled.
temporary  1. POOH w  2. Clean  3. Set CI  4. Circul will b  This well	abandonment:  ith rods, pump, and production out wellbore to 6850'. BP @ 6680' just above existing ate packer fluid and pressure out and pressure out and prior to		30 minut <b>e</b> s. The BLM t.
14. I hereby certify to	that the foregoing is true and forrect  Ti	de <u>Sr. Conservation Coordina</u>	- T
	TRIG. SGD.) TOE G. LARA	PETROLEUM ENGINEER	Date 7/1/94
Approved by	proval, if any: See or Hached.	Test to be performed willfully to make to any department or agency of the United	71 2150.

or representations as to any matter within its jurisdiction.

## BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

## Temporary Abandonment of Wells on Federal Lands

## Conditions of Approval

According to 43 CFR 3162.3-4-c, " No well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer".

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County call (505) 887-6544; for wells in Lea County call (505) 393-3612.
- A bridge plug or packer shall be set at a maximum of 50 feet above any open perforations or open hole.
- 3. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- 4. The production casing shall be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leak-off.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for 12 months provided that the operator:

- Submits a subsequent Sundry Notice requesting TA approval,
- 2. Attaches a clear copy or the original of the pressure test chart,
- 3. And attaches a detailed justification why the well should not be plugged and abandoned.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test.

- If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:
  - 1. A procedure to repair the casing so that a TA approval can be granted.
  - 2. A procedure to plug and abandon the well.