

(SUBMIT IN TRIPLICATE)

Land Office Las CrucesLease No. 031670 (a)Unit N.M.P.U.UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

RECEIVED

AUG 3 - 1951

ON CONSERVATION COMMISSION

HOBBS OFFICE

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

SEM-U-Burger A-19 No. 9

Hobbs, New Mexico

August 2, 19 51

Well No. 9 is located 1980 ft. from N line and 1980 ft. from E line of sec. 19NE/4 Sec. 19

(1/4 Sec. and Sec. No.)

20-3

(Twp.)

38-E

(Range)

N.M.P.M.

(Meridian)

Stargis

(Field)

Lea

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 10 3/4" casing at 265' with 225 sacks cement. Plug down 7:30 P.M.  
7-29-51. Cement circulated.On 7-30-51, after 2 1/2 hrs. NOI., tested casing with 250# for 30 minutes  
before drilling plug, final pressure 250#. Drilled out cement and tested  
casing with 250# for 30 minutes, final pressure 245#.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil CompanyAddress Box CCHobbs, New Mexico

By \_\_\_\_\_

Title District Superintendent

