

SUNDRY NOTICES AND REPORTS ON WELLS

1. oil ☒ gas ☐ other

2. NAME OF OPERATOR

Continental Oil Company

3. ADDRESS OF OPERATOR

Box 460, Hobbs, N.M. 88240.

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1650' FNL + 710' FEL

AT TOP PROD. INTERVAL: 52 M.D.

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE

CHANGE ZONES

ABANDON*

(other) Soft 7" Prod CS9

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

measured and true vertical depths for all markers and zones pertinent to this work.)*
Drill 8 3/4" hole from 1419' to 6760' T.D. Ran 7" 23# + 26#
K-55 CSG set at 6760'. DV Tool set at 3950'. Cmt'd
1st stage w/580 sx of class "c" cmt with additives. opened
DV Tool and circ. for 6 Hrs. Cmt'd 2nd stage w/575-sx of
class "c" cmt with additives. Plug down at 11:45 A.M. 4-23-78.
Rel. Rig at 3:00 P.M. 4-23-78. Shut-in w.o. Compl. Rig.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Wm. A. Butterfield TITLE Admin. Supv. DATE 9-29-18

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY: _____

ACCEPTED FOR RECORD
DATE *C.C.T.*
APR 26 1978
U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

*See Instructions on Reverse Side

USGS (5), NMFC (4), F, 1e