
Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No.

BOKEAU OF LAND MANAGEMENT		LC 031695B
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals		6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well Oil Gas ST CIA/ O		8. Well Name and No.
□ Well □ Gas Well ☑ Other SW D 2. Name of Operator		Warren Unit No. 24
Conoco, Inc.		9. API Well No.
3 Address and Telephone No.		30-025-07856
10 Desta Dr. Ste 100W, Midland, TX 79705 (915) 686-6548		10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		San Andres
24' FSL & 2145' FEL		11. County or Parish, State
Sec. 29, T-20S, R-38E		Lea
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
Subsequent Report	Recompletion Plugging Back Casing Repair	New Construction Non-Routine Fracturing Water Shut-Off
Final Abandonment Notice	Altering Casing Other	Conversion to Injection Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log (orm.)
 Describe Proposed or Completed Operations (Clearly state a give subsurface locations and measured and true vertice) 	li pertinent details, and give pertinent dates, including estimated date of starting cal depths for all markers and zones pertinent to this work.)*	g any proposed work. If well is directionally drilled
This SWD well recently failed a repair a bad section of casing injection by the following prod	a casing integrity test and is shut-in to restore casing integrity and retur cedure:	. It is proposed to n the well to
section just below 5 1/2" (4. Cement 4" liner in place w: 5. Drill out cement. RIH with	ith 95 sxs cement injection tubing and packer.	JAN
5. Set injection packer at 447	75° and return to injection.	
(See diagram on back)		= CEVE
		30.
14. I hereby certify that the foregoing is true and correct		
Signed Jem WHoods	Tide Sr. Conservation Coordinat	or Date 1/30/96
(This space for Federal of State office use)	RA Tide PETROLEUM ENGINEER	S/14/96
Approved by Conditions of approval, if any:	Title	Date
		-

PROPOSED CASING REPAIR



1-10-78

Wellburg Dirgam WAREN Chit #24

NMFU Az Mario