(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Form Approved.
Las Cruces
Land Office

Lease No. 1031695 A Unit E

SUNDRY NOTICES AND REPORTS ON WELLS

DEPAIR WELL	SUBSEQUENT REPORT OF ALTERING CASING SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT SUPPLEMENTARY WELL HISTORY OF CLEAN OLD
(IN DICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)	

| SEMU McKee | SEM

The elevation of the derrick floor above sea level is 3528 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

REFORE WORKOVER: TD 9400 SD & SHALE, PB 9151 DF, DF 12, ELEV 3516 AGL.

PAY MCKEE 8986-9125. CSG PT 5-K" AT 9398. PERFS 8985 9008, 9037,

9054, 9067, 9095 & 9125. ON TEST DATED 4-7-63, GL 22 BO, 1 BW W/GAS

TSTM IN 24 HRS. DAILY ALLOW IN AUGUST, 1963, 42 BO. WORK DONE: CLEANED

OUT SAND TO 9148. TRTD PERFS 8986-9125 W/SAND CONSOLIDATION TRUST.

RAN CHAMBER TYPE GAS LIFT EQUIPMENT. AFTER WORKOVER: TD, PB, DF, ELEV,

PAY, CSG PT & PERFS - SAME AS BEFORE WORKOVER. ON POT GL 67 BO, 3 BW

IN 24 HRS. GRAVITY 43.2. CP 550, TP 150. EST DAILY ALLOW 67 BO.

WORKOVER STARTED 8-3-63, COMP SEB-63, TSTD 8-12-63. LOCATION: 1980.

FNL & 990 FWL, SEC. 29-20-38. CONDCO W.I. 25 PC.

Company Continental Cil Company

Address Box 68 - Eunice. New Mexico

USGS-4 NBOCC-2 ABS FILE

PAN AM-HBS-3 ATL-ROSW-2

CALIF CIL-HOUS, MID-1 Each

Title District Superintendent