

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Las Cruces
Lease No. 1670 (a)
Unit H.F.U.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

~~STEELE~~ Burger A-30 No. 2~~Hobbs~~, New Mexico~~September 21~~ 1950Well No. 2 is located 660 ft. from N line and 190 ft. from E line of sec. 30N 1/4 30 30
(1/4 Sec. and Sec. No.)20
(Twp.)30
(Range)1875C
(Meridian)Shawnee
(Field)Lin
(County or Subdivision)New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 3537 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 7" casing at 3699' and cemented with 1920 sacks cement. Total depth of hole 3700' in line. Plug down 10:30 P.M. 9-11-50. Top of cement behind pipe 600' by Temperature Survey.

On 9-12-50, Tested casing with 1200' for 30 minutes. Final pressure 1160'. Found top of cement plug at 3651. Drilled out cement plug and tested casing with 1200' for 30 minutes. Final pressure 1150'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil CompanyAddress Box 00Hobbs, New Mexico

By

Title District Superintendent

