

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Murphy H. Baxter, 102 V & J Tower, Midland, Texas
(Address)

LEASE State "H" WELL NO. 1 UNIT N S 36 T 20S R 38E

DATE WORK PERFORMED 2/22/55 POOL D. K. Albo

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☒ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

The hole was filled with heavily laden mud and a 25 sack cement plug was run at total depth, casing was shot loose and a 25 sack cement plug was run in the stub of 5-1/2" casing at approx. 5432'; a 15 sack cement plug was run in the bottom of the 8-5/8" casing at approx. 998'; a 10 sack cement plug was run in the bottom of the 12-3/4" at approx. 315'; a 15 sack cement plug was run in the top and a 4" marker placed 5' above the ground.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____	_____ (Company)	

OIL CONSERVATION COMMISSION

Name [Signature]
Title [Signature]
Date 2/22/55

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name Alan Antweiler
Position Agent
Company Murphy H. Baxter
Midland, Texas