



(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. LC-056011(a)
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 10, 1957

Well No. 1 is located 330 ft. from S line and 660 ft. from W line of sec. 8
SW/4, Sec. 8 T-21-S R-38-E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Littman (San Andres) Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3563 ft. DF

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Loaded hole with mud. Spotted plugs as follows: 25 sacks - 4327'-4266'
25 sacks - 3164'-3085'
25 sacks - 2757'-2678'
25 sacks - 1754'-1675'
Pulled 8 5/8" casing. Spotted plugs as follows: 25 sacks - 180'-149'
10 sacks - In surface

Rig moved out and location completely cleared May 25, 1957.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company MWJ Producing Company
Address 118 Central Building
Midland, Texas

By R. K. Villan

Title Vice-President & Treasurer