

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p>
		<p>5. State Oil & Gas Lease No.</p>
<p>1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-</p>		<p>7. Unit Agreement Name</p>
<p>2. Name of Operator IMPERIAL AMERICAN MANAGEMENT COMPANY</p>		<p>8. Farm or Lease Name Eunin</p>
<p>3. Address of Operator 215 Mid America Building, Midland, Texas 79701</p>		<p>9. Well No. 2</p>
<p>4. Location of Well UNIT LETTER <u>E</u> <u>660</u> FEET FROM THE <u>West</u> LINE AND <u>1980</u> FEET FROM THE <u>North</u> LINE, SECTION <u>18</u> TOWNSHIP <u>21S</u> RANGE <u>38E</u> NMPM.</p>		<p>10. Field and Pool, or Wildcat Wantz Abo</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.)</p>		<p>12. County Lea</p>

<p>16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p>			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Status Report

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was T/A in September, 1972 pending a study of recompletion possibilities.

It was non commercial from this zone.

Expires 11/1/75

The ownership of this property is in reorganization under Chapter X of the Federal Bankruptcy Act. The Trustee of the corporation has not been able to provide funds for the necessary examination of work-over potential. It is anticipated that the company's reorganization will be complete in the latter quarter of 1975 and that funds will then be available to examine the property for workover possibilities and to perform the workover if justified. We request that adequate time be given for this contingency prior to the forced plugging and abandonment of the well. The lease is being held by production from the Bunin Well No. 5, and there is no danger of losing the lease.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Agent DATE 10/26/74

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: