



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office San Antonio

Lease No. 1774

Unit 1

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 10, 1961

Well No. 2 is located 600 ft. from N line and 600 ft. from W line of sec. 7

Sec. 7 (1/4 Sec. and Sec. No.) 12 (Twp.) 34 (Range) 10N (Meridian)  
Indiagatad (Field) 1883 (County or Subdivision) San Antonio (State or Territory)

The elevation of the derrick floor above sea level is 3523 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was drilled to a TD of 6500' with no commercial production encountered.

It is our intention to plug and abandon this well in the following manner; cement off 7" cas. at 3515' and pull pipe, set plugs at 3165-3200' 40 sz, 3500-3650' 40 sz, 1300-1300' 40 sz, 400-300' 40 sz and 15 sz at surface, fill intervals between plugs with 10 lb mud, erect marker and return to original condition.

Approval obtained from Mr. J. J. Wadley, District Engineer, L.A. 11-6-61.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address P.O. Box 68

San Antonio, New Mexico

1/2 section 2-34-10 file

By J. B. Lusk

Title District Superintendent