

(SUBMIT IN TRIPLICATE)

U. S. Land Office.....

Has Graces

046853

Lease or permit No.....

Faye H. Saunders

Allottee.....

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Lease No.....

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Midland, Texas - August 13, 1937

Well No. **2** is located **660** ft. from **N** line and **661.8** ft. from **E** line of sec. **9**  
**NW/4 of NW/4 of Sect. 9 22-South 34-East**  
**San Simon** (Field) **Lea** (County or Subdivision) **New Mexico** (State or Territory)  
 (Twp.) (Range) (Meridian)

The elevation of the derrick floor above sea level is **3898** ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run 1092' of 12-1/2" casing at 1109' on August 10, 1937. Casing not Cemented - will be pulled later.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Humble Oil & Refining Company**Address **Box 1600 - Midland, Texas**By *W. B. Sanders*Title **Division Superintendent**