

(SUBMIT IN TRIPLICATE)

U. S. Land Office Las Cruces

Lease or permit No. 046335

Raye H. Saunders

Allottee.....

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Lease No.....

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Midland, Texas July 12, 1937

Well No. 3 is located 660 ft. from N line and 661.8 ft. from EX line of sec. 9

N 1/4 of N 1/4 of Sect. 9 22-South 34-East
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
San Simon Lee New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3598 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 294' of 15-1/2" casing at 300' on June 20, 1937. Hole casing badly.
Ran additional 70' of 15-1/2" casing on July 7, 1937. Casing not cemented -
will be pulled later.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining Company

Address Box 1600 - Midland, Texas

By W. H. Saunders

Title Division Superintendent

Indian Agency.....

(SUBMIT IN TRIPLICATE)

U. S. Land Office **Las Cruces**

UNITED STATES

~~XXXX~~ permit No. **046533**

Allottee.....

DEPARTMENT OF THE INTERIOR

Faye H. Saunders

Lease No.....

GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Midland, Texas **July 12,** 19 **37**

Well No. **2** is located **660** ft. from **N** line and **661.8** ft. from **W** line of sec. **9**

N¹/₄ of N¹/₄ of sec. 9

(¹/₄ Sec. and Sec. No.)

22-South 34-East

(Twp.)

(Range)

(Meridian)

San Simon

(Field)

Lee

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is **3898** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run 61' of 20" casing at 74' - not cemented. Will be pulled later.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Humble Oil & Refining Company**

Address **Box 1600 - Midland, Texas**

By

Title **Division Superintendent**