

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

DEC 22 1 23 PM '66

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B-9445</b>

### SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Skelly Oil Company</b>	8. Farm or Lease Name <b>State "U"</b>
3. Address of Operator <b>P. O. Box 730, Hobbs, New Mexico</b>	9. Well No. <b>2</b>
4. Location of Well UNIT LETTER <b>N</b> <b>1980</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM <b>East</b> <b>5</b> TOWNSHIP <b>22-8</b> RANGE <b>35-E</b> NMPM.	10. Field and Pool, or Wildcat <b>San Simon</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3606' DT</b>	12. County <b>Lea</b>

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> <b>Plug and Abandon</b>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Moved in and rigged up Pulling Unit; pulled rods and tubing.
- Spotted 55-sack cement plug from 3640-4130'.
- Cut and pulled 7"OD casing from 688'.
- Spotted 35 sacks of cement across top of 7"OD casing to 600'.
- Spotted 55 sacks of cement across bottom of 16"OD casing back to 39'.
- Spotted 10 sack cement cap at surface and installed 4' X 4" steel dry-hole marker.
- All intervals not cemented were filled with heavy mud laden fluid.
- Plugging operations completed and well abandoned December 19, 1966.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

(ORIGINAL)  
(SIGNED) **H. E. Aab**

SIGNED \_\_\_\_\_ TITLE **District Superintendent**

DATE **December 20, 1966**

APPROVED **Leslie A. Clemente** TITLE \_\_\_\_\_

DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: