

STATE N.M.	COUNTY Lea	ELEVATION 	DESC. BY VILAS P. SHELDON, ARTESIA, NEW MEXICO	COMPANY Casper Drilling Co.
KIND OF SAMPLES Rotary	LOCATION 	DATE 12 22 35	FARM Dan's Sub C	WELL NO. 3

DEPTH	SOLIDS		DESCRIPTION	SALT		SHALE				SAND			CHT	NOTES
	%	LINE		%	ANHY	RED	GRY.	GRN.	BLK	RED	GRY.	DESCRIPTION	%	
3120-10				100										
3120-50				80	20									
3120-80					100									
3120-10	20		tan		20									
3120-20	60		white		40									
3120-30	20		buff		80									
3120-50					100									
3120-60	40		buff sandy		60									
3120-80	100		white											
3120-90	100		white											
3120-100	50		gray											
3120-20	100		buff											
3120-30	80		gray											
3120-40	30		buff	10						60				
3120-50	10		gray	30	20					30				
3120-60				20	30					20		F.g.g.		
3120-70				70						30		white		
3120-80	20		gray	10	20					50		white		
3120-90	40		white	10						50		white		
3120-100	80		white							20		might be OK		
3120-10	80		white							20		F.g.g.		
3120-20	60		white							40		might be OK		
3120-30	70		white							30		buff		
3120-40	40		white							60		some oil staining		
3120-50	50		white							50				
3120-60	80		buff							20				
3120-70	80		white							20				
3120-80	30		buff							30				
3120-90	90		white							10				
3120-100	100		white											
3120-10	90		white							10				

