

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-85

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
E-8173

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection Well	7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation	Field Yates Sand Unit
3. Address of Operator Box 670, Hobbs, New Mexico 88240	8. Farm or Lease Name
4. Location of Well UNIT LETTER P , 660 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 14 TOWNSHIP 22-S RANGE 35-E NMPM.	9. Well No. 143
15. Elevation (Show whether DF, RT, GR, etc.) 3583' GL	10. Field and Pool, or Wildcat Jalmat
	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

Plugged and abandoned.

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

3965' TD, 3955' PB.

Could not release packer at 3777'. Cut and recovered tubing from 3770', leaving 7' of 2-1/16" tubing and Larkin packer in hole. Ran CI BP and set at 3750'. Circulated hole with gel water. Spotted 5 sack cement plug on top of BP. Spotted 10 sack cement plug from 2000' to 1850', across salt. Spotted 10 sack cement plug from 100' to surface. Installed dry hole marker and cleaned location. Plugged and abandoned June 18, 1974.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>B. J. Barbant</u>	TITLE <u>Area Engineer</u>	DATE <u>June 18, 1974</u>
APPROVED BY <u>John W. Rungan</u>	TITLE <u>Controller</u>	DATE <u>SEP 13 1974</u>
CONDITION OF APPROVAL, IF ANY:		