

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS
(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY The British American Oil Producing Company - Box 2818, Midland, Texas
(Address)

LEASE New Mexico "B" WELL NO. 4 UNIT A S 14 T-22-S R-35-E

DATE WORK PERFORMED See Below POOL Undesignated

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off

☒ Beginning Drilling Operations

☐ Remedial Work

☐ Plugging

☒ Other Surface Casing

Detailed account of work done, nature and quantity of materials used and results obtained.

1. Well spudded 5:00 P.M., May 18, 1956.
2. 3-5/8" O.D., 22.7 Arco spiral weld casing set to 334' K.B. May 19, 1956, cemented with 180 sacks. Cement circulated.
3. Tested surface casing with 750' for 30 minutes. Casing tested ok.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____

Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____

Perf Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test

Oil Production, bbls. per day

Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by _____

(Company)

OIL CONSERVATION COMMISSION

Name Cecil H. Brandon

Title District Superintendent

Date MAY 23 1956

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name Cecil H. Brandon

Position District Superintendent

Company The British American Oil Prod. Co.