


for

SCOUT REPORT NEW MEXICO

OIL CONSERVATION COMMISSION



Company CONTINENTAL
 Farm Name LOCKHART "B"-1 Well No. 3
 Land Classification _____
 Sec. 1- Twp. 22 Range 36 County Lea
 Feet from Line: N. 1980 S. 1980 E. _____ W. _____
 Elevation _____ Method Rotary
 Contractor Mara Scout _____
 Spudded 12-5-38 Completed 1-1-39 Initial Production _____
 Bond Status _____

ACID RECORD

Casing and Cementing Record Amount

Size	Feet	Inches	Sax Cement
<u>10 3/4</u>	<u>277</u>		<u>200</u>
<u>7 5/8</u>	<u>1151</u>		<u>425</u>
<u>2</u>	<u>3786</u>		

Gals.

Prod.	Date
Prod.	Date
Top Pay <u>3730</u>	Total Depth _____
No. of Quarts <u>180</u>	SHOOTING RECORD
No. of Quarts _____	Shot at <u>3730</u> Feet <u>3802</u>
	Shot at _____ Feet _____

Date		Date	
<u>11-28-38</u>	<u>Cellar & Pits</u>	<u>1-10</u>	<u>T.D. 3802 L</u>
<u>12-6</u>	<u>T.D. 280 RR</u>		<u>I.D. 6030 show</u>
	<u>Ring 205</u>		<u>3/4 F</u>
<u>DEC 1 31938</u>	<u>T.D. 1230A</u>		<u>324 M Gas</u>
	<u>WOC</u>		
<u>DEC 20 1938</u>	<u>A+L- 3140</u>		
<u>12-28</u>	<u>3685 L- 6001 C.</u>		
<u>JAN 4 - 1939</u>	<u>T.D. 3802 L</u>		
	<u>Tstg</u>		
	<u>4 W at 3685</u>		
	<u>6 BDPH</u>		
	<u>8 BDP + Gas</u>		
	<u>6030 show</u>		
	<u>3/4 F</u>		
	<u>324 M Gas</u>		

LOG

[illegible]