

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETION OPERATION		REPORT ON ACIDIZING (Other)	X

July 25, 1952

(Date)

El Paso, New Mexico

(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

Continental Oil Company

(Company or Operator)

State of

(Lease)

(Contractor)

Well No.

1

in the

NE 1/4

SW 1/4

of Sec.

2

T. 23S, R. 34E, NMPM,

Artesian

Pool,

Sea

County.

The Dates of this work were as follows:

7-10-52

Notice of intention to do the work (was) ~~not~~ submitted on Form C-102 on

7-8-52

(Cross out incorrect words)

19

and approval of the proposed plan (was) ~~not~~ obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

The subject well was flowing no oil and 19 bbls. water per day.

The openhole section from 3497' to total depth 3517' was acidized with 500 gallons acid.

After acidizing, flowed 35 bbls. oil and 32 bbls. water per day.

Work commenced 7-10-52

Work completed 7-10-52

Witnessed by

(Name)

(Company)

(Title)

Approved:

OIL CONSERVATION COMMISSION

Roy Yarbrough

(Name)

(Title)

(Date)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name

J. R. Smith

Position

Dist. Mgr. El Paso

Representing

Continental Oil Company

Address

Box 427, El Paso, New Mexico