

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C 103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

P.O. Drawer DD, Artesia, NM 88210

DISTRICT TII  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30-025-08825
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	State 'A' A/C 2
8. Well No.	19
9. Pool name or Wildcat	Jalmat, Tnsi, Yts, 7-Rivers (Pro Gas) (79240)

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Raptor Resources, Inc.	
3. Address of Operator 901 Rio Grande, Austin, TX 78701	
4. Well Location Unit Letter <u>O</u> <u>660</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>7</u> Township <u>22S</u> Range <u>36E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-31-99 MIRU Sierra Well Service. GIH W/ 5 1/2" csg scrapper & tbg to PBTD @ 3527', attempt to circ hole W/ 2% KCl wtr. Had returns below csg head. Dug out & found 5 1/2" csg collapsed above top collar & surface Head, POOH W/ tbg & scrapper. Cut & remove abad section of csg. Weld bell nipple on new section 5 1/2" csg & replace.  
11-2-99 RU WL perf Yates W/ 2 SPF @ 3362, 3364, 3374, 3376, 3378, 3385, 3401, 3404, 3412, 3417, 3420, 3422, 3424, 3434, 3437, 3450, 3467, 3475, 3478, 3482, 3499, 3502, 3509, 3518 & 3523 total of 52 holes, RD. GIH W/ model R 5 1/2" pkr set @ 3267', spot 250 gal acid across perfs. Acid Yates perfs W/ 1750 gal 15% HCl w/ 100 BS.  
11-3-99 RU BJ Frac Yates W/ 22,650 gal 40# linear gel binary foamed to 70 quality w/ 123 T CO2 & 633 MCF N2 w/ 179,500# 12/20 Brady sand. RD  
11-10-99 GIH release pkr POOH w/ tbg & pkr. GIH W/ tbg tag sand fill # 3435'. Clean out sand from 3435-3527, pull tbg up to 3200'.  
11-12-99 GIH W/ 106 jts 2 3/8" tbg set @ 3372'. GIH W/ 2" X 1 1/2" X 12' hollow-valve rod pump & rods.  
11-13-99 RDMO Return the well to production.

Test dated 11-23-99: 0 BO, 4 BW, 45 MCF

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bill R. Keathly TITLE R regulatory Agent for Raptor DATE 1-17-00  
TYPE OR PRINT NAME Bill R. Keathly TELEPHONE NO. 915-697-1609

(this space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

20 T... ..