(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR CILIC Service III Compa GEOLOGICAL SURVEY

Land Office	ias Cres	0 0
Lease No.	30132-8	
Lease No		
Cle	seen apa	

SUNDRY NOTICES AN	ID REPORTS ON WELLS
NOTICE OF INTENTION TO DRILL NOTICE OF INTENTION TO CHANGE PLANS NOTICE OF INTENTION TO TEST WATER SHUT-OFF NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL NOTICE OF INTENTION TO SHOOT OR ACIDIZE NOTICE OF INTENTION TO PULL OR ALTER CASING NOTICE OF INTENTION TO ABANDON WELL	SUBSEQUENT REPORT OF ABANDONMENT
(INDICATE ABOVE BY CHECK MARK N	ATURE OF REPORT, NOTICE, OR OTHER DATA)
	April 10 , 19.57
Vell No. 2 is located 660 ft. from (1/2 Sec. and Sec. No.) (Twp.)	$ \begin{cases} N \\ S_{\text{S}} \\ \text{ line and } \end{cases} $ line of sec. 19 $ \frac{36-2}{\text{Range}} \qquad $
	Subdivision) (State or Territory)
Remodial work is not feasible since No. 1 and 4 with negative results in	40, as a producing oil well at 3820'. Producial status and water to over 90% prior to 5. attempts were made on both Closson "B" Wells both instances.
It is proposed to plug and abandon to loading hole with mud, spotting 35 se	he well by reclaiming all pescible 53° casin was of coment to plug open hole extending in ment at the point where 53° casing is shot-of
	n writing by the Geological Survey before operations may be commenced.
Company Cities Service Oil Company	4
Address	
Habbe, New Yex 100	Title
<u>-</u>	Title Statutet Superinterient
	The state of the s