

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Dalport Oil Corporation				Address 930 Fidelity Union Life Bldg Dallas, Texas		
Lease L. Lunt "B"	Well No. 1	Unit Letter P	Section 20	Township 22S	Range 36E	
Date Work Performed 1-30-63	Pool Jalmat Gas			County Lea		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☐ Casing Test and Cement Job ☒ Other (Explain):
☐ Plugging ☐ Remedial Work **Set bridge plug**

Detailed account of work done, nature and quantity of materials used, and results obtained.

1. Pulled 106 joint 2" EUE tubing with Guiberson packer
2. Set Halliburton cast iron bridge plug @ 3329' on wire line using Kelly bushing measurement.
3. Ran 3167' tubing - KB measurement, 3160' measured from top tubing head.

Witnessed by Leon M. Lampert	Position Geologist	Company Dalport Oil Corporation
--	------------------------------	---


FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P BTD	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.	
Approved by 	Name Leon M. Lampert		
Title	Position Geologist		
Date	Company DALPORT OIL CORPORATION		