

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-100  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER - <b>SUN OIL</b>		7. Unit Agreement Name
2. Name of Operator <b>Sunray DX Oil Company</b>		8. Firm or Lease Name <b>D.B. Boren</b>
3. Address of Operator <b>P.O. Box 128, Hobbs, New Mexico</b>		9. Well No. <b>2</b>
4. Location of Well UNIT <b>P</b> 1980 FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM <b>East</b> LINE, SECTION <b>20</b> TOWNSHIP <b>22</b> RANGE <b>36</b> NMPM.		10. Field and Pool, or Wildcat <b>South Eunice</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>D.F. 3559</b>		12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
REPAIR OR ALTER CASING <input type="checkbox"/>	

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <b>Drill Deeper (48')</b> <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up cable tools & clean out to T.D. 3852'. Drill to T.D. 3900'.
2. Placed 16.3 hydromite plug 3908-3898 (W.L. measure) Perf 2 holes @ 3638, 3644, 3654, 3658. Acidized w/500 gal. BDA.
3. Ran tbg. & rods & put well on pump. Test for 8 BO @ 12 BW in 24 hrs.

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B.F. Brawley TITLE District Engineer DATE 5-11-65

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: