

HOBBS OFFICE OCC

NEW MEXICO OIL CONSERVATION COMMISSION

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106) 9:09

Company Dalport Oil Corporation, 930 Fidelity Union Life Bldg., Dallas, Texas
(Address)

Lease Annie L. Christmas Well No. 1 Unit 0 S 21 T 22-S R 36-E

Date work performed 9-4-55 POOL South Eunice

This is a Report of (Check appropriate block) ☒ Result of Test of Casing Shut-off

☐ Beginning Drilling Operations

☐ Remedial Work

☐ Plugging

☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

**Cemented 305' of 9-5/8" O. D. 32.30# Seamless Casing with 200 sacks.
Cement circulated. Tested with 500#s.
Tested OK**

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl. Date _____

Tbng. Dia. _____ Tbng. Depth _____ Oil String Dia _____ Oil String Depth _____

Perf. Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test

Oil Production, bbls. per day

Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by _____

(Company)

Oil Conservation Commission

Name

Title

Date

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name

Position

Company

Vice-President

Dalport Oil Corporation