



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Form Approved.

Land Office Las Cruces
Lease No. 10 031620 b
Unit 10112

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Skaggs B-12

March 18, 1963, 19

Well No. 5 is located 990 ft. from (N) line and 1700 ft. from (W) line of sec. 12

NE/4 SW/4 Sec. 12 20-S 37-E T10N
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
NMFO La New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3582 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Spud at 2:00 P.M., 3-17-63. Ran 1432' 9 5/8" OD 36 1/2 lb 40 casing, set at 1434' with 450 sacks cement with 4% gel. Plug down at 4:30 P.M., 3-17-63. Cement circulated. 24 hours. Tested casing with 1000 PSI for 30 minutes before and after drilling plug. Tested o.k.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 68

Alameda, New Mexico

By SIGNED: J. E. PARKER

Title District Superintendent

USDA-3 18000-2 148 File