

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE
(Other instructions on reverse side)Form approved,
Budget Bureau No. 42-R424

5. LEASE DESIGNATION AND SERIAL NO.

LC-031621 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	RECEIVED JAN 8 1970 U.S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO	7. UNIT AGREEMENT NAME NMI-U
2. NAME OF OPERATOR Continental Oil Company		8. FARM OR LEASE NAME BRITT B
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, New Mexico 88240		9. WELL NO. 18
4. LOCATION OF WELL (Report location clearly and in accordance with any State law. See also space 17 below.) At surface 660' FSL + 1980' FWL of Sec. 10, T-20S, R-37E, Lea County, N. Mex.		10. FIELD AND POOL, OR WILDCAT Weir Blinby & Monument Tubb
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 10, T-20S, R-37E	12. COUNTY OR PARISH Lea	13. STATE N. Mex.
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, KY, CP, etc.) 3581' RT	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) <u>Downhole Commingle</u>	

(Other) Downhole Commingle

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

The monument Tubb & Weir Blinby are being downhole commingled. The following work has been performed.

Pulled and layed down Blinby tubing and rods. Released Tubb tubing leaving tailpipe in model 'D' packer. Ran 2 7/8" tubing with S.V. and set S.V. at 6321. Placed well back on production. Worked completed 12-31-69

18. I hereby certify that the foregoing is true and correct

SIGNED M. E. ParkerTITLE Adm. Section ChiefDATE 1-2-70

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

DATE

USGS-5 FILE

JAN 7 1970

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

M. E. Parker