FORM C-108 ITEM XI

ANALYSIS - SANTA ROSA WATER

POGO PRODUCING COMPANY Proximity "31" Federal #4 Section 31, TWP 22-S, R 32-E

Lea County, New Mexico

Chemical and radiochemical analyses of water from test hole H-5

EXHIBIT 4

Water produced from the Santa Rosa Sandstone, sample taken 5/24/78

Alkalinity Field (mg/l as HCO3)	200
Bicarbonate FET-FLD (mg/l as HCO3)	240
Nitrogen, NO2 + NO3 Dissolved (mg/l as N)	0.36
Hardness (mg/l as CACO3)	150
Hardness, noncarbonate(mg/l as CACO3)	150
Calcium Dissolved (mg/l as CA)	56
Magnesium, Dissolved (mg/l as MG)	51
Sodium, Dissolved (mg/l as NA)	280
Potassium, Dissolved (mg/l as K)	25
Chloride, Dissolved (mg/s as CL)	120
Sulfate, Dissolved (mg/l as SO4)	530
Fluoride, Dissolved (mg/l as F)	1.2
Silica, Dissolved (mg/l as SIO2)	11.0
Boron, Dissolved (ug/l as B)	890
Solids Residue at 105 Deg C, Dissolved (mg/l)	1200