

APPROVED

(SUBMIT IN TRIPLICATE)

JUN 8 1964

UNITED STATES

DEPARTMENT OF THE INTERIOR

J. L. GORDON

GEOLOGICAL SURVEY

ACTING DISTRICT ENGINEER

Land Office New MexicoLease No. 1101-04405Unit P

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Bass-FederalJune 41964Well No. 1 is located _____ ft. from N line and _____ ft. from E line of sec. _____SE 1/4 Sec. 19
(1/4 Sec. and Sec. No.)22-S
(Twp.)32-E
(Range)NM PM
(Meridian)Village
(Field)Lea
(County or Subdivision)New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 3610 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

ON June 1, 1964 Set 7" 23# J-55 STAC Surface Casing at 460'. Cemented With 400 Sacs regular Cement. Cement Circulated. after 24 hours pipe tested with 1500# for 30 minutes. Pipe Tested O.K.

Well Spudded on May 30, 1964.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Ralph LoweAddress Box 832Midland, TexasBy E. J. [Signature]Title agent