STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION DISTRIBUTION BANTA FE SANTA FE, NEW MEXICO 87501	Ford C-103 Revised 10-1-78
	Sa. Indicate Type of Lesse State Fee 5. State Oli 6 Gas Lesse No. B-1557
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO GETPEN OF PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" IFORM C-1011 FOR SUCH PROPOSALS.)	
1. OIL X GAB OTHER.	7, Unit Agreement Name 8. Form of Lease Name
2. Nome of Operator Amoco Production Company 3. Address of Operator	State "C" Tract 13
P. O. Box 68, Hobbs, New Mexico 88240	9. Well 190. 9 10. Field and Pool, or Wildcat
4. Location of Well UNIT LETTERF1980 FEET FROM THE NORTH LINE AND1980 FEET FROM	Tubb-Drinkard
THE West LINE, SECTION 36 TOWNSHIP 21-S RANGE 37-E NMPM.	
3368' RDB	12. County Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Oth	
NOTICE OF INTENTION TO: SUBSEQUENT PERFORM REMEDIAL WORK	ALTERING CASING
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JQB	
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1903.	
Moved in service unit 9-11-83. Pulled rods and pump. Removed tree and installed blowout preventer. Pulled tubing. Recovered packer at 6380'. Ran 7" retrievable bridge plug, 1 joint 2-3/8" tailpipe, 7" packer, 2-3/8" seating nipple, and 2-3/8" tubing. Bridge plug set at 6599' and packer set at 6309', landing tailpipe at 6344' and seating nipple at 6308'. Pumped 4200 gal 15% NEFE HCL acid and 210 gal Welchem G-15 with additives. Flushed. Reset the retrievable bridge plug at 6350' and the packer at 5997', landing tailpipe at 6032'. Loaded backside and pumped 4600 gal 15% NEFE HCL acid and 230 gal Welchem G-15 with additives. Flushed and swabbed. Pulled tubing, seating nipple, retrievable bridge plug, packer, and tailpipe. Ran 2-3/8" seating nipple, 15 joints 2-3/8" tubing, 7" tubing anchor, and 2-3/8" tubing. Seating nipple landed at 6590' and anchor set at 6126'. Removed blowout preventer and installed tree. Ran rods and pump. Moved out service unit 9-21-83. Pump tested for 144 hours and pumped 87 BO, 131 BW, and 169 MCF. Last 24 hours pumped 17 BO, 16 BW, and 40 MCFD. Returned well to production.	
0+5-NMOCD,H 1-HOU, R. E. Ogden, Rm 21.150 1-F. J.Nash, HOU Rm 4.206	1-CLF
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	10.10.00
Assist. Admin. Analyst	10-18-83
APPROVED BY CHUNCHTON TITLE DISTRICT I SUPERVISOR	DCT 20 1983
CONDITIONS OF APPROVAL IF ANY	

