

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-031736(6)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	8. FARM OR LEASE NAME
PAN AMERICAN PETROLEUM CORPORATION	GILLULY 'B' Federal
3. ADDRESS OF OPERATOR	9. WELL NO.
BOX 68, HOBBS, N. M. 88240	13
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT
2086 ENL x 1874 FEL Sec. 22 (Unit G, S1/4 NE1/4)	NEIR FORWARD
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	22-20-37 N.M.P.M
3451 R.D.B.	12. COUNTY OR PARISH 13. STATE
	LEA N.M

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

In an effort to increase productivity of well, Isolated lower 2nd perf 6731-6838. Put a Bridge Plug set @ 6738. Separated intervals 6600-02, 24-23, 38-44, 48-52, 64-74, 80-82, 86-89, 91-96, 6702-06 w/2550F. Acidized w/5000 gal LSTNE. Evaluated. Pumped 32 BW w/Trace of oil. Shut in for evaluation and possible P & A.

TD - 7805'
PBD - 7310'

13 7/8" CSA 324'
9 5/8" CSA 377'
5 1/2" CSA 7805'

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

Area Engineer

5/4/70

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

0-4- USGS-W
1- ACJR
1- SUSP
1- RRY

*See instructions on Reverse Side

ACCEPTED FOR RECORD
MAY 5 1970
GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

RECEIVED

MAY 12 1970

OIL CONSERVATION COMM.
HOBBES, H. H.